



Wiring the keypad to an electric strike failed locked



Keypad

Power Supply



Electric Strike

